

INSPECTION REPORT REVIEW
POTENTIAL HAZARDOUS WASTE SITE

SITE NAME : Wiley Post Airport

LOCATION : Bethany, Ok

SITE NUMBER: OKD987070059

SURVFY DATE: 11/14 / / INSPECTED BY: STATE FIT TAT OTHER:

LABORATORY : CLP EPA OTHER

RECEIVED FROM: William Taylor DATE RECEIVED: 555R 9/4/91 10/10/91

SAMPLE TYPE(s):

SOIL	SURFACE WATER	GROUND WATER	DRINKING WATER
off / on -site	off / on -site	off / on -site	off / on -site

CONTAMINANT(s): Organics Inorganics Radionuclides Microbiological

FOLLOW UP (Y/N):

<u> </u> (Re)Sampling Requested	<u> </u> Locate Drinking Water Sources
<u> </u> Further Action is URGENT	<u> </u> Keep Site Active ("N"=No Further Action)
	<u> </u> Concur with Report Recommendations

SUMMARY: Water Supply had reviewed a Screening Site Inspection Report for this site on 10/1/91 and did not recommend further sampling at this site.

RECOMMENDATION: Concur with Superfund recommendation for no further action.
Do not recommend further sampling at this site.

Concurrence:

P. Warren Lewis 10/18/91

Edgar A. Jeffers 10/18/91
ENGINEER/REVIEWER

9831279

